

Appendix M

Photographic Log of Test Pitting

**Northwest Boundary Area RCRA Facility Investigation
Fort Buchanan, Puerto Rico**



Photo 1: Re-bar from TP-1.



Photo 2: TP-2, little debris found.



Photo 3: Setting up on TP-3. TP-1, TP-2 in foreground.



Photo 4: Debris from TP-3. Wood and metal scrap.



Photo 5: Coiled rubber found in TP-3.



Photo 6: Test pits filled in and field repaired after digs.



Photo 7: Begin excavating TP-4.



Photo 8: Canisters found in TP-4, approximately 2-4 ft deep.



Photo 9: Close-up of canisters found in TP-4.